Oil Field Environmental Incident Summary

Responsible Party: TRIANGLE USA PETROLEUM CORPORATION **Well Operator:** TRIANGLE USA PETROLEUM CORPORATION

Well Name: Simpson 151-102-5-8-1H

Field Name: ELK Well File #: 28817

Date Incident: 3/8/2015 Time Incident: 14:00 Facility ID Number:

County: MCKENZIE Twp: 151 Rng: 102 Sec: 5 Qtr: NE NE

Location Description:

Submitted By: Brittany Vannoy Received By:

Contact Person: Brittany Vannoy

1200 17TH ST., SUITE 2600 1200 17th Street Suite 2600 DENVER, CO 80202-5826

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 10 Barrels 8 Barrels

Description of Other Released Contaminant:

Frac Fluid

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Tuesday, March 24, 2015 Page 1 of 2

Potential Environme None.	ental Impacts:	
Action Taken or Pla		
Spill cleaned with vac	cuum truck and hauled to disposal.	
Wastes Disposal Lo	ocation:	
Agencies Involved:		
Updates		
Date: 3/11/2015	Status: Reviewed; O&G Lead	Staff: Stockdill, Scott
Updated Oil Volum	e:	
Updated Salt Water	r Volume:	
Updated Other Vol	ume:	
Updated Other Cor	ntaminant	
Notes:		

According to the incident summary, this spill remained on location. NDIC retains oversight.

Tuesday, March 24, 2015 Page 2 of 2